

| | | | |
|-----------------------------------|-------------------------------|---|-----------------|
| STATE ✓ Virginia | COUNTY King William | TOWN OR VICINITY Rumford vicinity | 6s 10p 30 |
| INDEX NUMBER VA. 51-Rumford, 1 | MONUMENT Moeser House | | |
| REPRESENTED IN NEGATIVE FILE | H.A.B.S. SURVEY NO. VA-154 | Owner: Chalkley Beverley (colored) Date built: early 19th C. Builder: German immigrant, Moeser. Condition: ruinous | |
| PUBLISHED PHOTOGRAPHS | | Description: One story below two stories in roof; of logs squared, halved at corners up to gable line, above which ends studded; prob ably no weatherboarding originally; gable roof, once shingled; windows two-leaf case- ments; hand-wrought iron hardware; plan: single large room first floor, winding ✓ | |
| PUBLISHED DRAWINGS | | | |
| FN. 108 | | | |
| GPO 6-8369 | | 10-444 HISTORIC AMERICAN BUILDINGS SURVEY 90 | |

corner stair; entrance door north and south, one window to east in each case; east wall chimney modern (house may have been heated by porcelain stoves); second floor until 1939 had sheathed partitions making two bedrooms to east, hall and hall room to west; stair well constructed.

Prepared by Thomas T. Waterman 1941